

McLennans Diving Service

- Marine Contractors

Unit 15, 75 Corish Circle, PAGEWOOD Australia 2035 – Postal: PO Box 6209 Malabar NSW 2036
Phone +61 (02) 9700 0885 email@mclennan.com.au www.mclennan.com.au

To Hannah Curtis
Department of Crown Lands

From Alan McLennan
Project Manager

12th June 2023

LTMMP Inspection of ex-HMAS Adelaide wreck May 2023

McLennans Diving service (MDS) inspected ex-HMAS Adelaide to carry out the requirements of the Long-Term Monitoring and Management Plan (LTMMP) for structural condition monitoring. This report covers the requirements of that Plan and includes inspection of the barred off areas in the upper superstructure and Ultrasonic Thickness (UT) testing of the six Monitoring locations. MDS Divers carried out the survey of the wreck on May 12th, May 30th, 31st and June 1st, 2023.

The Dive Team was supervised by Alan McLennan and Daniel Fell with divers Zoe Pocklington, Stafford Malapa, Louis Dupressoir. All the divers hold ADAS Part 2 or 3 qualifications and are experienced naval ship inspectors. The team operated from the 2C surveyed vessels "Sea Runner" and "Cape Diver". The diving method was a combination of SCUBA buddy pairs, SCUBA using AGA Divator masks with hard wired voice communications. Also used was the Deep Trekker Revolution ROV.

The first day of the survey on May 12th was abandoned after the first dive due to zero visibility water clarity below 22 metres. The dive team returned after favourable reports from other divers indicating good conditions for three continuous days.

Executive Summary

The vessel has not changed its position or list. No deterioration has been observed on the steel hull. The aluminum superstructure continues to deteriorate rapidly due to corrosion and cracking. However, the past year has not created any new damage to the vessel but rather a worsening of the existing damage. There are no new dangers for recreational divers compared to last year.

Results of the survey

Hull Integrity –

The vessel can be divided horizontally into two halves. The top half is the aluminum superstructure and the lower half below the main deck, is the steel hull.

The Steel Hull - The lower half of the vessel has suffered little or no deterioration since the sinking. This continues to be the case. No corrosion, cracking or displacement of fittings was observed on the outside or inside of the steel hull. All entrance ways inspected were clear. All long-term monitoring points were inspected, and no deterioration was found since our last inspection. These locations were:

- the Missile launcher opening,
- the Forward screen,
- the Hangar frames.
- the Transom

In addition, this year we conducted a complete circuit of the wreck at the seabed to examine the hull at the sand line. This was done using our Deep Trekker Revolution ROV. We found that the paint coatings are intact on the steel hull down to just above the seabed. At this point there is a band of bare metal about 500mm wide caused by the abrasion of the sand. See **Figure 9**. No corrosion was observed on any parts of the steel hull.

We also noted the diverse and colourful fixed plant life on all parts of the side of the steel hull. This is not only a sign of a healthy marine environment, but it also indicates that no corrosion is occurring in the steel hull, as marine growth does not adhere to rusting surfaces. See **Figure 8**.

The Aluminum Superstructure - The upper half of the vessel has continued its steady rate of deterioration. There is very widespread corrosion. The outer sheeting is heavily corroded along the welds to the stringers and frames and in the center of the panels. The frames are heavily corroded at the frame connections. The corrosion is not uniform. Some panels are heavily corroded, and some appear to be unaffected. See **Figures 16 and 17**.

The aluminum panels and frames are welded to the steel hull along a 100mm high vertical steel flat bar that extends at right angles from the main deck. These aluminum panels and frames have commonly broken at this joint. The aluminum superstructure has reached a state of deterioration where additional panels would be expected to be broken out with every large swell event. See **Figures 3 and 4**.

There have been numerous new openings created into the aluminum superstructure along the 01-deck by the swell surge. These are shown in the attached drawing. In general, when these panels break out, it is a clean break, and no further attention is required.

Swinging Panels

MDS found two swinging panels in 01 deck. The first panel forms the inside wall of the starboard hanger. The second swinging panel is on the port side of the weather shield. The details of these two panels follow below:

Swinging Panel 1 – Starboard Hanger - Interior wall. – This wall once formed the inboard wall of the starboard hanger. On one side of it was the starboard hanger, and on the other was the central access companionway from the flight deck. This wall has broken along the joint to the steel hull and is swinging freely. It was held in place by its connections to the upper decks. The swinging wall dimensions were 8 metres long by 2.5 metres high. Initially MDS believed the swinging part of the wall extended to the top of 02 deck.

The wall currently presents no danger to divers in calm sea states. In seas over 2 metres, it moves violently over 300mm and could be dangerous. This wall will fall after a large sea in the foreseeable future. It requires monitoring to look for cracks that would indicate that the collapse is imminent. At this time our divers found no cracks into upper part of the wall to suggest the failure is imminent. See the video at this link [Starboard Hanger Broken Wall Video](#)

Swinging Panel 2 – Weather Shield – Port side –Exterior wall – A panel 2.5 metres high and 700mm wide is swinging with the swell surge. It is moving only slightly in calm seas and would not present any danger except in seas of over 2 metres when it can move violently. **See Figure 10**

Siltation in the forward Spaces

An opening was cut into the 01-deck wall just aft of the weather shield in June 2022 to allow water flow into the forward compartment behind the weather shield. A large amount of silt had built up in this space during the 2022 floods. This area is now clear of silt and only coarse shell mounds remain which present no siltation hazard to a diver. No new areas of silt were found.

Barred Off areas – The 32 barred off areas on Page 25 of Annex A of the LTMMP were examined and all bars were found to be in place except for the destroyed Hangar Catwalks and Captain's Bathroom. **See Figure 5**

Vessel List and Trim - The wreck remains at the same list as in previous years at approximately 4 degrees to port. This was determined by use of digital depth gauges on the gunwales amidships and a spirit level placed on the hangar deck. **See Figures 6 and 7.** The trim of the vessel was also unchanged.

The sand level was deeper than previous years. Both bilge keels were fully exposed, and part of the sonar dome. The duckbill on the transom was just under the sand.

LTMMMP Monitoring Locations –Thickness Testing

In addition to visual monitoring, the locations were also thickness tested at three separate points close to the monitoring point. The method used was as follows at each area to be measured:

- An area was selected for testing and its position was recorded.
- An area 100mm in diameter was scraped clean.
- An Olympus 26MG ultrasonic thickness gauge with a 60-metre-long probe cable was used to measure the metal thickness. The probe was placed on the cleaned area and the diver notified the surface team by two-way voice communications.
- When a stable reading was achieved the Diving Supervisor recorded the thickness and told the diver to move to the next location.
- The thickness test results were recorded in the table below.

Location – Main Deck except for Location 6	Frame Number	Recorded thickness (mm)				
		Nominal	2020	2021	2022	2023
1 – Hangar Deck – 300mm aft of the centre pillar –	335	6.35	6.79	6.8	6.68	6.66
2 – 300mm off the change in shape at waist on the port side -	180	7.95	7.73	7.68	7.70	7.65
3) 300mm off the change in shape at waist on the starboard side -	180	7.95	8.01	8.08	7.99	7.92
4) 300mm off the base of the weather shield – port side	100	6.35	7.53	6.88	7.20	7.12
4) 300mm off the base of the weather shield – port side	100	6.35	6.51	6.5	6.45	6.49
5) 300mm off the missile launcher opening	85	9.52	10.9	9.57	9.58	9.57
6) Base of main mast 02 deck	Too corroded to measure					

Thickness Testing Conclusion

There has been no significant change to the steel thickness. This agrees with our visual observation that no corrosion is present on the steel surfaces and all paint coatings are intact.

LTMMP Monitoring Locations – Visual Monitoring

The Divers made note of the monitoring items listed in the LTMMP Locations 1 to 6.

- Location 1 – The hull plating on the forecastle just aft of where the GMLA launcher. There has been no deterioration in this area.
- Location 2 – Amidships at the base of the forward weather screen (where the superstructure and hull are bonded together) – There is no visible deterioration in this area. There is no sign of any separation between the forward screen and the hull.
- Location 3 - At the vertical midpoint of the main masts – The mast appears to be in a similar condition as 2021. The entire main mast was examined however the mast is heavily encrusted with marine life restricting a detailed examination. There appears to be no sign of cracking or deformation. All parts of the mast remain straight and true. The base of the mast was also closely examined, and no sign of cracking or deformation were observed.
- Location 4 – The connections of the masts to the 02 deck. There is no sign of any deterioration in the legs. No cracking or deformation was observed. However, the aluminum plating that the legs pass through has severely corroded.
- Location 5 – The hull plating on the transom – The transom area has changed very little since the sinking.
- Location 6 – Where the helicopter hangars are attached to the hull. The port side hanger broke away completely in March 2021. The entrance to the starboard hanger is intact but the interior wall has separated from the deck. The exterior wall is missing.
- Internal Debris – The internal openings were clear of debris when last inspected on June 10th 2022. Since our last inspection there is an increased number of loose fittings such as floor mats, panels, cupboards which are laying loose inside the vessel but are not currently blocking any access ways or impeding divers.

Moorings

Both Special Markers were intact and in position. There were four mooring buoys present. No buoy was located on the stern. The mooring coming off the main mast is in poor condition due to chafing of the connection sling on the structure. **See Figure 20.**

This is because the moorings have not been installed with an underwater float as in previous years. As a result, the slack mooring rope/sling settles on the structure and chafes. The main mast mooring is extremely chafed. MDS divers attached an underwater float to it to prevent further chafing. This mooring should be replaced. The other mooring were in fair condition but also lacked an underwater float.

Marine Life

The marine life is bountiful and diverse. There are numerous ecosystems being supported by the wreck site. The type of ecosystem depends on the depth of water. The mast still holds dense plant life. **See Figures 8 and 21.** The lattice work mast of the wreck still attracts many schooling bait fish such as the Yellowtails, and predator fish such as Kingfish, Cobia, and John Dory. In most of the internal compartments we found a Wobbegong shark. Some are three metres long. The proximity of these creatures may cause distress to inexperienced divers when swimming through enclosed spaces in the wreck.

Safety for Recreational Divers

The wreck has reached a state of deterioration which means that the panels and frames in the aluminum superstructure will fail regularly. This creates new risks for recreational divers, especially the inexperienced. These risks include entrapment, snags, crush injuries and disorientation. The most important control for diver safety is training and supervision. The provision of detailed briefings and divemaster services with local knowledge will greatly reduce the risk to inexperienced divers. Verification of competency (VOC) through certification and logbook checks will also enhance safety. MDS recommends that extra vigilance be given to the above points in view of the deterioration in the vessel.

Recommendation for Further Monitoring

It is certain that major structural collapses will occur within the aluminum superstructure soon due to its advanced state of corrosion and loss of structural supports. This is especially likely in the starboard hanger.

We recommend that the vessel be surveyed after each 5 metre or greater swell event to check for cracking in the key support structures. This will reduce the likelihood of the structure collapsing unexpectedly.

The aluminum superstructure will continue collapsing for a long period into the future until finally only the steel hull is remaining. This hull will last a very long time without deterioration.

Conclusion

All parts of the LTMMP were completed. The wreck is safe for recreational diving within the generally accepted limits for training and experience. The wreck has not much changed since our last visit in June 2022. This period has been marked by unusually calm seas along the NSW coastline. This has reduced the rate of deterioration of the wreck compared to the start of 2022 which featured multiple East Coast Lows and large seas.

The starboard hanger continues to be a source of concern because its collapse would be expected after a large seas event.

Thank you for asking us to undertake this inspection. Please find following drawing and photos that illustrate the points made in this report.

Kind Regards

Alan McLennan
Phone 0433 111 528




Figure 1: Plan view of the hangers, the red line shows the separated wall to deck connection. The double red line shows the swinging wall




Figure 2: View of the starboard hanger from the port side showing the swinging wall




Figure 3: A section of the main deck and aluminum superstructure showing the join between the two. This weld has separated around the entire starboard hanger.



Figure 4: An example of the separation of the hanger wall from the steel deck



Figure 5: A selection of barred off openings. All barred off barriers were intact.




Figure 6: A view of a depth gauge on the port and starboard gunwales amidships. The beam is 14 metres. The one metre difference in height for a beam of 14 metres gives a list of 4 degrees 5s which is the same as in previous years.





Figure 7: The spirit level method gives a list to starboard of 3 degrees 50s.



Figure 8: Diverse and abundant fixed marine life on the sides of the steel hull.



Figure 9: A typical view of the hull at the seabed. The paint coating are abraded off the hull, but no corrosion is occurring.



Figure 10: The swinging panel at the starboard walkway through the weather shield.



Figure 11: The main mast continues to remain undamaged and all connections are intact.




Figure 12: One of the thickness testing locations cleaned and ready for testing.

No significant changes were recorded from last year.



Figure 13: The bridge area remains unchanged.



Figure 14: This is a view from No.2 deck through the wall of the lift shaft to the open starboard side.

The lift shaft walls have been significantly broken down in the last year. This has made the wreck interior more accessible and brighter.



Figure 15: Typical missing outer wall on 01 deck. The aluminum panels have "blown out" in many places. However, it has aided light entry into the interior and has not created new dangers.



Figure 16: This is a typical aluminum frame and stringer on the exterior wall of 01 deck. The walls are breaking down due to cracking and corrosion and then the panels break off the superstructure.



Figure 17: An example of the corrosion in the heat affected zones of the stringer connections to the frames.




Figure 18: Corrosion of the Aluminum superstructure continues to increase dramatically each year.




Figure 19: A view of the 02 deck with severe corrosion of the aluminum paneling




Figure 20: The main mast mooring is extremely chafed due to rubbing on the mast,



Figure 21: The mast is in sound condition and is heavily encrusted with colourful marine life.

Ex HMAS Adelaide May 2023

Legend



Missing or loose panel



Broken wall connection

